

**KANTHAL RORSVETMASKIN
RoR DIAM.OCH BANDBREDD**

www.electrolux.com.mk

tolerans B= \pm 0,10

t= \pm 0,014

1 F	4,76x0,71=13,13	41 F	12,0x0,75=35,7
2 F	5,0x0,40=14,8	42 F	12,0x1,0=35,0
3 F	6,0x0,40=18,0	43 F	12,0x1,5=33,5
4 F	6,15x0,40=18,4	44 F	12,5x1=36,6
5 F	6,35x0,5=18,75	45 F	12,7x0,65=38,2
6 F	6,35x0,6=18,4	46 F	12,7x0,75=37,9
7 F	6,68x0,46=19,9	47 F	12,7x0,8=37,9
8 F	7,0x0,5=20,8	48 F	12,7x1,3=36,3
9 F	7,1x0,6=20,8	49 F	13,0x1,2=37,5
10 F	7,14x0,45=0,5=21,35	50 F	13,0x1,5=36,7
11 F	7,2x0,4=21,7	51 F	14,0x0,70=42,15
12 F	7,2x0,5=21,4	52 F	14,0x0,75=42,0
13 F	7,5x0,40=22,5	53 F	14x0,8=41,9
14 F	7,5x0,5=22,35	54 F	15,0x1,0=44,4
15 F	7,5x0,6=22,1	55 F	15,0x1,3=43,55
16 F	8,0x0,4=24,2	56 F	15,0x1,5=43,0
17 F	8,0x0,5=23,9	57 F	15,88x1=47,2
18 F	8,0x0,6=23,6	58 F	15,88x1,3=46,3
19 F	8,0x0,65=23,5	59 F	16,0x0,75=48,3
20 F	8,0x0,7=23,3	60 F	16,0x1,0=47,6
21 F	8,0x0,8=23,0	61 F	16x1,3=46,7
22 F	8,5x0,50=25,5	62 F	18x0,90=54,1
23 F	9,0x0,75=26,3	63 F	19,05x1,3=56,3
24 F	9,5x0,50=28,6	64 F	19,05x1,5=55,7
25 F	9,5x0,6=28,35	65 F	22,0x1,3=65,5
26 F	9,5x0,65=28,2	66 F	22,0x1,5=64,9
27 F	9,5x0,7=28,1	67 F	25,4x1,3=76,2
28 F	9,5x0,75=28,0	68 F	25,4x1,5=75,6
29 F	10,0x0,4=30,3		
30 F	10,0x0,45=30,3		
31 F	10,0x0,5=30,2		
32 F	10,0x0,60=29,9		
33 F	10,0x0,65=29,8		
34 F	10,0x0,70=29,6		
35 F	10,0x0,75=29,5		
36 F	10,0x0,80=29,5		
37 F	10,0x1,0=28,7		
38 F	10,5x0,65=31,3		
39 F	10,5x0,75=31,0		
40 F	12,0x0,5=36,5		

**MATERIJALI LENTI ZA
SITE TIPOVO NA CEVKI**

Electrolux-Bitola

www.electrolux.com.mk

BANDBREDD B=(Dnt-t)xll
ex 8,0x0,5=(8,0-0,38)xll=7,62xll=23,9
tolerans.B= \pm 0,1mm(sirina)
t= \pm 0,015 -0,035(debelina)